



Gulfstream IV-1988


Aircraft Specification



[Click here to book](#)



Gulfstream IV-1988



The large stand-up cabin will accommodate up to 12 passengers in a luxurious setting.

Features

- ☐ Worldwide wireless internet (Gogo domestic)
- ☐ Worldwide satellite phone
- ☐ Full gourmet galley
- ☐ Open Bar
- ☐ Entertainment system with CD and DVD
- ☒ Airshow

Seats

- ☒ Four forward captain's chairs
- ☐ Four mid captain's chairs
- ☒ Four place conference with a 2-place kibitzer

Berths

- ☒ Four single beds
- ☐ One double bed

Capabilities

- ☐ Cruising Speed: 550mph
- ☐ Range: 4,987 statute miles
- ☐ Duration: 9.0 hours
- ☒ Cruising Altitude: 45,000 feet

Exterior Paint: 15 Aug 1994

Interiors: Aug 2021

[Click here to book](#)



Gulfstream IV-1988

ENGINE TYPE

Model: ROLLS-ROYCE TAY611-8

Engine:	Left	Right
Total Hours:	15,264.6	15,264.6
Hours Since New:	15,264.6	15,264.6
Cycles	6226	6226
Engine MIDLIFE (120MOS) Complied With	24 Sep 2012	24 Sep 2012
ENGINE OVERHAUL (240MOS) Complied With	10 Jan 2005	10 Jan 2005
OVERHAUL NEXT DUE	21 Sep 2024	21 Sep 2024

LANDING GEAR

Engine:	Left	Right	Nose
OH Acomplish	28 Jun 2002	28 Jun 2002	01 Apr 2009
Landings Since OH	4592	4592	22862
Remaining for OH	405 lnd	405 lnd	405 lnd

APU Type:

HONEYWELL GTCP36-100(G) Serial

Number: APUS: 6801

[Click here to book](#)



Gulfstream IV-1988

AVIONICS

Honeywell AZ-810 Air Data Module FMS Navigation
Computer NZ2000 Honeywell Bendix King GPS sensor unit
HG2021GD02 HONEYWELL RADAR RT/ANTENNA
7012640-904
Collins Aerospace DME-442 PN: 622-7309-101
Honeywell Radio Altimeter RT-300.
L3HARRIS™ DMH21-1 Diplexer, L VOR/ILS
Collins Aerospace TDR-94D Mode S Transponder IRU UNIT,
LASER HG1075AE04 Honeywell MK V EGPWS Computer
Honeywell TCAS II Change 7.1 4066010-914 Collins
Aerospace APP-65A Autopilot Control MagnaStar C-2000
P/N 724855-802 Honeywell AFIS DMU 400-045500-0003
Collins Aerospace VHF-422D 8.33 VHF Comm
Maintenance **performed** - Banyan Air Service
24/48 Month inspection 144/192 Month inspection Out of
phase inspections

[Click here to book](#)



Gulfstream IV-1988

COMPONENTS REPLACED THROUGHOUT THE SERVICE

DESCRIPTION	PN	QTY	APROXIMATE COST (USD)	
ANTI-ICE VALVE	979432-4-1	2	\$	30,000.00
OUTFLOW VALVE	2100378-1-1	1	\$	4,000.00
APU RPM INDICATOR	1159SCF407-9	1	\$	5,000.00
TCAS COMPUTER	4066010-914	1	\$	26,900.00
HYDRAULIC PUMP	63195	1	\$	13,000.00
HYDRAULIC RESERVOIR	1159H20126-7	1	\$	8,000.00
DRIVE ROD BOOT	43083-818-2	1	\$	5,000.00
CABIN WINDOW	1159CE20034-47	1	\$	22,793.00
RH MLG Door	1159B20017-2	1	\$	22,142.00
CABIN WINDOW	1159CE20034-45	2	\$	45,586.00
Approximate Cost			\$	182,421.00

[Click here to book](#)



Gulfstream IV-1988



[Click here to book](#)



Gulfstream IV-1988



[Click here to book](#)



Gulfstream IV-1988



[Click here to book](#)